

NOTICE OF NOTAM PUBLICATION

To: PHX NOTAM NOTIFICATION GROUP DISTRIBUTION

Date: 07/14/2026

From: DAGOBERTO HINOJOS
Aviation Supervisor II-Operations, (602) 273-2008

Subject: **PHX NOTAM #200-2026**


FAA NAS NOTAM # 07/065

OBSTRUCTION – 280' CRANE


USE CAUTION FOR A FLAGGED AND LIGHTED CRANE 280' AGL, 1,422' MSL AND LOCATED 9,960 FEET SOUTHEAST OF THE RUNWAY 25R THRESHOLD.

EFFECTIVE: SATURDAY, JULY 18, 2026 FROM 0600 (L) UNTIL 2359 (L).

**CRANE
COORDINATES:
33 24 51.04N
111 58 02.58W**



Smiley Lifting Solutions- Benji Harrison (480 268 6049)
2026-AWP-5760-OE
(9,960' SE RWY 25R & 1.64NM SE RWY 25R)


DAGOBERTO HINOJOS
Aviation Supervisor II- Operations

PHX NOTAMS IN EFFECT: #001-2026, 003-2026, 004-2026, 005-2026, 006-2026, 009-2026, 053-2026, 064-2026, 073-2026, 079-2026, 095-2026, 134-2026, 135-2026, 139-2026, 143-2026, 170-2026, 171-2026, 178-2026, 179-2026, 195-2026, 196-2026, 197-2026, 198-2026, 199-2026 AND 200-2026.

TO VIEW ALL CURRENT NOTAMS FOR PHX PLEASE VISIT: <http://notams.aim.faa.gov/notamSearch/> (USE LOCATION SEARCH WINDOW AND TYPE IN PHX)

PHX USE ONLY:

CANCELLED ON: DATE:

TIME:

REVIEWED BY:

FSS Operator Initials:



Mail Processing Center
Federal Aviation Administration
Southwest Regional Office
Obstruction Evaluation Group
10101 Hillwood Parkway
Fort Worth, TX 76177

Aeronautical Study No.
2026-AWP-5760-OE

Issued Date: 05/13/2026

SMILEY LIFTING SOLUTIONS
JOHN PUDLAS
5326 W. Mohave St.
Phoenix, AZ 85043

SAT 7/18 6500-1200
9,960 SE Rwy 25R
1.64 NM SE Rwy 25R

****DETERMINATION OF NO HAZARD TO AIR NAVIGATION FOR TEMPORARY STRUCTURE****

The Federal Aviation Administration has conducted an aeronautical study under the provisions of 49 U.S.C., Section 44718 and if applicable Title 14 of the Code of Federal Regulations, part 77, concerning:

Structure: Crane Mobile Crane 1345/S/52ND/ST
County, State: Maricopa, Arizona

Collected Point(s):

Label	Latitude	Longitude	SE	DET AGL	AMSL
pt-1	33-24-51.04N	111-58-02.58W	1142 Ft	280 Ft	1422 Ft

This aeronautical study revealed that the temporary structure does exceed obstruction standards but would not be a hazard to air navigation provided the condition(s), if any, in this letter is (are) met:

****SEE ATTACHMENT FOR ADDITIONAL CONDITION(S) OR INFORMATION****

This determination is based, in part, on the foregoing description which includes specific coordinates, heights, frequency(ies) and power. Any changes in coordinates, heights and frequencies or use of greater power, except those frequencies specified in the Colo Void Clause Coalition; Antenna System Co-Location; Voluntary Best Practices, will void this determination. Any future construction or alteration, including increase to heights, power or the addition of other transmitters, requires separate notice to the FAA. This determination includes all previously filed frequencies and power for this structure.

This determination does include temporary construction equipment such as cranes, derricks, etc., which may be used during actual construction of a structure. However, this equipment shall not exceed the overall heights as indicated above. Equipment which has a height greater than the studied structure requires separate notice to the FAA.

This determination did not include an evaluation of the permanent structure associated with the use of this temporary structure. If the permanent structure will exceed Title 14 of the Code of Federal Regulations, part 77.9, a separate aeronautical study and FAA determination is required.

This determination concerns the effect of this temporary structure on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

A copy of this determination will be forwarded to the Federal Aviation Administration Flight Procedures Office if the structure is subject to the issuance of a Notice to Airmen (NOTAM).

If you have any questions, please contact our office at 1-817-222-4559, or luke.w.wray@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2026-AWP-5760-OE

Signature Control No: 698923701-703821621

(TMP)

Luke Wray

Specialist

Additional Condition(s) or Information for ASN 2026-AWP-5760-OE

Proposal: To construct and/or operate a(n) Crane to a height of 280 feet above ground level, 1422 feet above mean sea level.

Location: The structure will be located 2.52 nautical miles southeast of PHX Airport reference point.

Part 77 Obstruction Standard(s) Exceeded and Aeronautical Impacts, if any:

Section 77.17 (a) (2) by 80 feet - a height that exceeds 1342 feet above mean sea level within 2.52 nautical miles of PHX.

Section 77.17 (a) (5) a height that affects an Airport Surface by penetrating:

Section 77.19 (a) Horizontal Surface by 138 feet as applied to PHX.

Preliminary FAA study indicates that the above mentioned structure would:

have no effect on any existing or proposed arrival, departure, or en route instrument flight rules (IFR) operations or procedures.

have no effect on any existing or proposed arrival, departure, or en route visual flight rules (VFR) operations.

have no effect on any existing or proposed arrival, departure, or en route instrument/visual flight rules (IFR/VFR) minimum flight altitudes.

not exceed traffic pattern airspace

have no physical or electromagnetic effect on the operation of air navigation and communications facilities.

have no effect on any airspace and routes used by the military.

Based on this aeronautical study, the structure would not constitute a substantial adverse effect on aeronautical operations or procedures because it will be temporary. The temporary structure would not be considered a hazard to air navigation provided all of the conditions specified in this determination are strictly met.

As a condition to this Determination, the structure is to be marked/lighted in accordance with FAA Advisory circular 70/7460-1 M Change 1, Obstruction Marking and Lighting, flags/red lights-Chapters 3(Marked),4,5(Red),14(Temporary),&15.

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

It is required that the manager of PHOENIX SKY HARBOR INTL, (602) 273-3302 be notified at least 3 business days prior to the temporary structure being erected and again when the structure is removed from the site.

This determination expires on 11/13/2027 unless extended, revised, or terminated by the issuing office.

NOTE: REQUEST FOR EXTENSION OF THE EFFECTIVE PERIOD OF THIS DETERMINATION MUST BE E-FILED AT LEAST 15 DAYS PRIOR TO THE EXPIRATION DATE. AFTER RE-EVALUATION OF CURRENT OPERATIONS IN THE AREA OF THE STRUCTURE TO DETERMINE THAT NO SIGNIFICANT AERONAUTICAL CHANGES HAVE OCCURRED, YOUR DETERMINATION MAY BE ELIGIBLE FOR ONE EXTENSION OF THE EFFECTIVE PERIOD.

